

	A	B	C	D	E	F
1	Incident ID/#	Cause	Means of extinguishment	Fire Safety Systems in place	Occupant intervention prior to FRNSW arrival	Fatalities
2	3332505	Other electrical failure	Portable fire extinguisher, insufficient information ava Dry chemical AB ( E )	No smoke alarm present  Sprinklers - No equipment present in room or space of fire origin  Extinguishers and Hydrants installed	Yes	0
3	3223990	Incendiary, not during civil disturbance	Hose line Water only	No smoke alarm present  Sprinklers - No equipment present in room or space of fire origin  Extinguishers and Hydrants installed	No	0
4	3175668	Ignition factor undetermined	Carbon dioxide Portable Extinguishers	No smoke alarm present  Sprinklers - No equipment present in room or space of fire origin  Extinguishers, Hose Reel and Hydrants installed	No	0
5	3130491	Other electrical failure	Carbon dioxide Portable Extinguishers	Not reported	No	0
6	3034430	Not reported	Not reported	Not reported	Not reported	0
7	174721	Level 1: Accidental Level 2: Product/Equipment Failure/Deficiency Level 3: Overheating	CO2/ Carbon dioxide	Not reported	No	0
8	151225	Level 1: Accidental Level 2: Human Factor Level 3: Failure to maintain/clean	CO2/ Carbon dioxide	Alarms/Detectors Present YES Alarms/Detectors Operating YES Type of Alarm Smoke detector Sprinklers in Property NO Brigade Booster Installed in the vicinity? YES	Yes	0